



Date: November 11, 2010

SAFETY BULLETIN NOTICE – MOELLER MARINE PRODUCTS

FUEL LINE CONNECTORS:

Part Numbers: 033410-10, 033480-10, 033471-10, 033481-10, 033486-10, 033482-10

Please note these part numbers reflect individual packaged fuel line connectors.

Part Numbers: 034385-10LP, 034391-10LP, 034394-10LP, 034399-10LP, 034385-10, 034391-10, 034394-10, and 034399-10

Please note these part numbers reflect individual packaged fuel line assembly, with the fuel line connectors.

Moeller Marine Products has discovered that a small percentage of the assorted fuel line connectors, indicated above by part number, may be hard to connect to the mating male fuel line connector. This condition could exist from fuel line connectors manufactured and shipped from May 2010 until October 2010.

This notification is to make commerce aware of this concern. The fuel line connectors will still function as designed, but if there are questions related to this notice please contact Moeller Marine Products Customer Service Department immediately at 1-800-432-8344 or at moellerinfo@moellermarine.com

This condition does not occur in any of our other fuel line connectors, just the assorted part numbers above.

Moeller Marine Products
801 North Spring Street
Sparta, TN 38583
Tel: 1-800-432-8344